




CLUTCH SERVO					
	ALPAR#	REF	APPLICATION	Specifications	
	<b>H-286102</b>	970 051 102 0	DAF 658882, 262077, 624993 Iveco 04776623, 42064599 Mercedes A6992950018 Scania 1935585 BMC- Pro	1-4 / M14x1.5 11 / M16x1.5 21 / M16x1.5 Ø 75 STROKE 67	
	<b>H-286107</b>	970 051 107 0	MERCEDES BMC SCANIA	Ø 100 STROKE 58	
	<b>H-286111</b>	970 051 111 0	DAF 1518243 Iveco 02984590, 93156099 MAN 81307256026, 81307256027 Neoplan 040320400, 81307256026	1-4 / M14x1.5 11 / M16x1.5 21 / M16x1.5 Ø 75 STROKE 85	DAF 1518243 Iveco 02984590, 93156099 MAN 81307256026, 81307256027 Neoplan 040320400, 81307256026
	<b>H-286114</b>	970 051 114 0		1-4 / M14x1.5 11 / M16x1.5 21 / M16x1.5 STROKE 67	DAF 659807, 1519272R Irisbus 500362256 Iveco 01261885, 02477724 MAN 85300019892, 99114230001 Neoplan 040320200 Renault 5021170431 Scania 1935588 Van Hool 637209480 VDL Bus 20186981 ZF 0501204975
	<b>H-286124</b>	970 051 124 0	MERCEDES BMC SCANIA		
	<b>H-286126</b>	970 051 126 0		1-4 / M14x1.5 11 / M16x1.5 21 / M16x1.5 STROKE 85	
	<b>H-286127</b>	970 051 127 0		1-4 / M14x1.5 11 / M16x1.5 21 / M16x1.5 STROKE 58.5	
	<b>H-286128</b>	970 051 128 0		1-4 / M14x1.5 11 / M16x1.5 21 / M16x1.5 STROKE 58.5	



	<b>H-286129</b>	970 051 129 0		1-4 / M14x1.5 11 / M16x1.5 21 / M16x1.5 STROKE 85	
	<b>H-286130</b>	970 051 130 0		1-4 / M14x1.5 11 / M16x1.5 21 / M16x1.5 STROKE 85	
	<b>H-286131</b>	970 051 131 0 Ø 90	DAF - 1518247 DIMETAL - 461 404 0 VAN HOOL - 637208670 EVO-BUS - 8383231000 MERCEDES - 001 295 67 07		OPERATING PRESSURE :10 BAR STROKE : 72 MM PUSH-ROD : 700N ENERGY SUPPLY : M16 X 1,5 OIL INLET : M16 X 1,5
	<b>H-286146</b> <b>H-286147</b>	970 051 146 0 970 051 147 0	MERCEDES	<b>CLUTCH SERVO</b>	
	<b>H-286407</b> <b>H-286408</b>	970 051 407 0 970 051 408 0	MAN		
	<b>H-286413</b> <b>H-286423</b>  <b>H-286405</b> <b>H-286431</b>	970 051 413 0 970 051 423 0  970 051 405 0 970 051 431 0		<b>CLUTCH SERVO</b> MAX. OPERATING PRESSURE: 10 BAR STROKE: 85 DIA 102 PUSH-ROD REPAIR KITS FORCE: 6000 N M22X1.5 M14X1.5	
	<b>H-286126</b> <b>H-286430</b> <b>H-286441</b>	970 051 126 0 970 051 430 0 970 051 441 0			
	<b>H-28604</b>	622785AM		<b>CLUTCH SERVO</b>	
	<b>H-28658</b>	971 051 158 0	MERCEDES 403	<b>CLUTCH SERVO</b>	
	<b>H-28613</b>	321 019 001			



	<p><b>H-28700</b></p>	<p>VG3200</p>			
	<p><b>H-28621</b></p>	<p>VG3261</p>			
	<p><b>H-28624</b></p>	<p>VG3264</p>			
		<p>VG 3361</p>			